


1 YEAR
WARRANTY

MADE IN
USA



User's Guide



Shop online at

omega.com™

Ω OMEGA®

www.omega.com

e-mail: info@omega.com

ISO 9001
CERTIFIED
CORPORATE QUALITY
STAMFORD, CT

ISO 9002
CERTIFIED
CORPORATE QUALITY
MANCHESTER, UK

HX92A Series RELATIVE HUMIDITY TRANSMITTER



OMEGAnet® Online Service
www.omega.com

Internet e-mail
info@omega.com

Servicing North America:

USA:
ISO 9001 Certified
One Omega Drive, Box 4047
Stamford CT 06907-0047
Tel: (203) 359-1660 FAX: (203) 359-7700
e-mail: info@omega.com

Canada:
976 Bergar
Laval (Quebec) H7L 5A1
Tel: (514) 856-6928 FAX: (514) 856-6886
e-mail: info@omega.ca

For immediate technical or application assistance:

USA and Canada: Sales Service: 1-800-826-6342 / 1-800-TC-OMEGA®
Customer Service: 1-800-622-2378 / 1-800-622-BEST®
Engineering Service: 1-800-872-9436 / 1-800-USA-WHEN®
TELEX: 996404 EASYLINK: 62968934 CABLE: OMEGA

Mexico: En Español: (001) 203-359-7803 e-mail: espanol@omega.com
FAX: (001) 203-359-7807 info@omega.com.mx

Servicing Europe:

Benelux: Postbus 8034, 1180 LA Amstelveen, The Netherlands
Tel: +31 (0)20 3472121 FAX: +31 (0)20 6434643
Toll Free in Benelux: 0800 0993344
e-mail: nl@omega.com

Czech Republic: Rude' armády 1868, 733 01 Karviná 8
Tel: +420 (0)69 6311899 FAX: +420 (0)69 6311114
Toll Free: 0800-1-66342 e-mail: czech@omega.com

France: 9, rue Denis Papin, 78190 Trappes
Tel: +33 (0)130 621 400 FAX: +33 (0)130 699 120
Toll Free in France: 0800-4-06342
e-mail: france@omega.com

Germany/Austria: Daimlerstrasse 26, D-75392 Deckenpfronn, Germany
Tel: +49 (0)7056 9398-0 FAX: +49 (0)7056 9398-29
Toll Free in Germany: 0800 639 7678
e-mail: sales@omega.com

United Kingdom: One Omega Drive, River Bend Technology Centre
ISO 9002 Certified
Northbank, Irlam, Manchester
M44 5EX United Kingdom
Tel: +44 (0)161 777 6611 FAX: +44 (0)161 777 6622
Toll Free in United Kingdom: 0800-488-488
e-mail: sales@omega.co.uk

It is the policy of OMEGA to comply with all worldwide safety and EMC/EMI regulations that apply. OMEGA is constantly pursuing certification of its products to the European New Approach Directives. OMEGA will add the CE mark to every appropriate device upon certification.

The information contained in this document is believed to be correct, but OMEGA Engineering, Inc. accepts no liability for any errors it contains, and reserves the right to alter specifications without notice.

WARNING: These products are not designed for use in, and should not be used for, patient-connected applications.



WARRANTY/DISCLAIMER

OMEGA ENGINEERING, INC. warrants this unit to be free of defects in materials and workmanship for a period of **13 months** from date of purchase. OMEGA's Warranty adds an additional one (1) month grace period to the normal **one (1) year product warranty** to cover handling and shipping time. This ensures that OMEGA's customers receive maximum coverage on each product.

If the unit malfunctions, it must be returned to the factory for evaluation. OMEGA's Customer Service Department will issue an Authorized Return (AR) number immediately upon phone or written request. Upon examination by OMEGA, if the unit is found to be defective, it will be repaired or replaced at no charge. OMEGA's WARRANTY does not apply to defects resulting from any action of the purchaser, including but not limited to mishandling, improper interfacing, operation outside of design limits, improper repair, or unauthorized modification. This WARRANTY is VOID if the unit shows evidence of having been tampered with or shows evidence of having been damaged as a result of excessive corrosion; or current, heat, moisture or vibration; improper specification; misapplication; misuse or other operating conditions outside of OMEGA's control. Components which wear are not warranted, including but not limited to contact points, fuses, and triacs.

OMEGA is pleased to offer suggestions on the use of its various products. However, OMEGA neither assumes responsibility for any omissions or errors nor assumes liability for any damages that result from the use of its products in accordance with information provided by OMEGA, either verbal or written. OMEGA warrants only that the parts manufactured by it will be as specified and free of defects. OMEGA MAKES NO OTHER WARRANTIES OR REPRESENTATIONS OF ANY KIND WHATSOEVER, EXPRESS OR IMPLIED, EXCEPT THAT OF TITLE, AND ALL IMPLIED WARRANTIES INCLUDING ANY WARRANTY OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE ARE HEREBY DISCLAIMED. LIMITATION OF LIABILITY: The remedies of purchaser set forth herein are exclusive, and the total liability of OMEGA with respect to this order, whether based on contract, warranty, negligence, indemnification, strict liability or otherwise, shall not exceed the purchase price of the component upon which liability is based. In no event shall OMEGA be liable for consequential, incidental or special damages.

CONDITIONS: Equipment sold by OMEGA is not intended to be used, nor shall it be used: (1) as a "Basic Component" under 10 CFR 21 (NRC), used in or with any nuclear installation or activity; or (2) in medical applications or used on humans. Should any Product(s) be used in or with any nuclear installation or activity, medical application, used on humans, or misused in any way, OMEGA assumes no responsibility as set forth in our basic WARRANTY/DISCLAIMER language, and, additionally, purchaser will indemnify OMEGA and hold OMEGA harmless from any liability or damage whatsoever arising out of the use of the Product(s) in such a manner.

RETURN REQUESTS/INQUIRIES

Direct all warranty and repair requests/inquiries to the OMEGA Customer Service Department. **BEFORE RETURNING ANY PRODUCT(S) TO OMEGA, PURCHASER MUST OBTAIN AN AUTHORIZED RETURN (AR) NUMBER FROM OMEGA'S CUSTOMER SERVICE DEPARTMENT (IN ORDER TO AVOID PROCESSING DELAYS).** The assigned AR number should then be marked on the outside of the return package and on any correspondence.

The purchaser is responsible for shipping charges, freight, insurance and proper packaging to prevent breakage in transit.

FOR **WARRANTY** RETURNS, please have the following information available BEFORE contacting OMEGA:

1. Purchase Order number under which the product was PURCHASED,
2. Model and serial number of the product under warranty, and
3. Repair instructions and/or specific problems relative to the product.

FOR **NON-WARRANTY** REPAIRS, consult OMEGA for current repair charges. Have the following information available BEFORE contacting OMEGA:

1. Purchase Order number to cover the COST of the repair,
2. Model and serial number of the product, and
3. Repair instructions and/or specific problems relative to the product.

OMEGA's policy is to make running changes, not model changes, whenever an improvement is possible. This affords our customers the latest in technology and engineering.


OMEGA is a registered trademark of OMEGA ENGINEERING, INC.

© Copyright 2000 OMEGA ENGINEERING, INC. All rights reserved. This document may not be copied, photocopied, reproduced, translated, or reduced to any electronic medium or machine-readable form, in whole or in part, without the prior written consent of OMEGA ENGINEERING, INC.

	Page
General Description	1
Unpacking	1
Theory of Operation	2
Mounting	3
Terminal Connections	5
Transmitter Wiring Examples	5
RH Output Calculations	6
RH Measured Vs Output Reading	6
Calibration	7
Calibration Procedure For HX92AC	7
Calibration Procedure For HX92AV	8
Specifications	10

Figure		Page
Figure 1	Basic Set-up With Current Loop Output.....	3
Figure 2	Wall Mount Model Dimensions	3
Figure 3	Duct Mount Model Dimensions	4
Figure 4	Duct Mounting Kit Installation	4
Figure 5	Terminal Connections	5
Figure 6	Transmitter Wiring Examples - For Current Output Models	5
Figure 7	Transmitter Wiring Examples - For Voltage Output Models	5
Figure 8	HX92AC Typical Calibration Setup	8
Figure 9	HX92AV Typical Calibration Setup	9

HX92A SERIES Relative Humidity Transmitter



General Description

The OMEGA® HX92A Series Relative Humidity Transmitter provides a linearized and temperature compensated output signal of 4 to 20 mA or 0 to 1 Vdc depending upon model selected. The output signal has been calibrated to follow a 0 to 100% Relative Humidity output scale. A thin film polymer capacitor senses relative humidity and is protected by a stainless steel filter that is easily removed for cleaning. The NEMA rated polycarbonate enclosure and cable entry connection provides weathertight protection. Screws are provided for mounting via internal holes inside the enclosure.

Unpacking

Remove the packing list and verify that you have received all your equipment. If you have any questions about the shipment, please call our Customer Service Department at

1-800-622-2378 or 203-359-1660. On the web you can find us at:

www.omega.com e-mail: cservice@omega.com

When you receive the shipment, inspect the container and equipment for any signs of damage. Note any evidence of rough handling in transit. Immediately report any damage to the shipping agent.

NOTE

NOTE: The carrier will not honor any damage claims unless all shipping material is saved for inspection. After examining and removing contents, save packing material and carton in the event reshipment is necessary.

The following items are supplied in the box with your HX92A transmitter.

- This Manual, # M-1019A (1 ea.)
- #6 Wall Anchor and #6 Mounting Screw (2 ea.)



Additional Transmitter Models Available

Model	Description
HX93AC	Wall mount RH and Temperature transmitter (dual 4 to 20 mA Output)
HX93AV	Wall mount RH and Temperature transmitter (dual 0 to 1 Vdc Output)
HX93AC-D	Duct mount RH/Temperature transmitter (dual 4 to 20 mA Output)
HX93AV-D	Duct mount RH/Temperature transmitter (dual 0 to 1 Vdc Output)
HX15AV-W	Wall mount "High Ambient Temperature" application RH/Temperature transmitter (dual 0 to 1 Vdc Output)
HX15AC-W	Wall mount "High Ambient Temperature" application RH/Temperature transmitter (dual 4 to 20 mA Output)
HX15AV-D	Duct mount "High Ambient Temperature" application RH/Temperature transmitter (dual 0 to 1 Vdc Output)
HX15AC-D	Duct mount "High Ambient Temperature" application RH/Temperature transmitter (dual 4 to 20 mA Output)

Theory of Operation

A 4-20 mA loop is a series loop in which a transmitter will vary the current flow depending on the input to the transmitter. In the HX92A the amount of current allowed to flow in the loop will vary depending on the relative humidity being measured by the sensor. Some advantages of a current output over a voltage output is that the signal measured is less susceptible to electrical noise interference and the loop can support more than one measuring instrument as long as the maximum loop resistance is not exceeded.

A typical application utilizing a current loop will normally consist of a power supply, the transmitter and a meter, recorder or controller to measure the current flow. The loop resistance is the sum of the measuring instruments and wire used. The maximum allowable loop resistance for the HX92A to function properly is found by using the following formula:

$$R_{\max} = (\text{power supply voltage} - 6 \text{ volts}) \div .02 \text{ amps}$$

EXAMPLE: (When using a 24 Vdc power supply).

$$R_{\max} = (24 - 6) \div .02 \text{ amps} = 900 \text{ ohms max loop resistance}$$




Figure 1: Basic Transmitter Set-up With Current Loop Output.

Complimentary Instruments

Power Supply, OMEGA Model No.: PSU-93
 Csi32 Series Panel Meters and Controllers

Recommended Accessories

Shielded Transmitter Cable, OMEGA Model No.: TX4-100 (100 ft)
 RH Calibration Kit, OMEGA Model No.: HX92-CAL
 Duct Mounting Kit, OMEGA Model No.: HX90DM-KIT

Mounting

OMEGA’s HX92A transmitter is designed for either wall or duct mounting depending upon model. Plastic wall anchors and mounting screws are included for wall mounting. A duct mounting kit is also available for duct mount models. OMEGA Model No.: HX90DM-KIT




Figure 2: Wall Mount Model Dimensions mm (inches)



HX92A SERIES
Relative Humidity Transmitter




Figure 3: Duct Mount Model Dimensions mm (inches)




Figure 4: Duct Mounting Kit Installation



Terminal Connections

Models: HX92AC, HX92AC-D (Current Output)

1. + Power Supply
2. 4-20 mA Output
3. No Connection

Models: HX92AV, HX92AV-D (Voltage Output)

1. + Power Supply
2. - Power Supply
3. 0 - 1 Vdc Output




Figure 5: Terminal Connections

Transmitter Wiring Examples For Current Output Models (4 - 20 mA)




Figure 6: Transmitter Wiring Examples
For Current Output Models

For Voltage Output Models (0 - 1 Vdc)




Figure 7: Transmitter Wiring Examples
For Voltage Output Models



RH Output Calculations

To calculate % Relative Humidity by measuring the current or voltage output use the following formulas.

For current output: $\%RH = (\text{Current measured in miliamps} - 4) \div .16$

EXAMPLE: $(11.04 \text{ mA} - 4) \div .16 = 44 \%RH$

For voltage output: $\%RH = (\text{Voltage measured in volts} \times 100)$

EXAMPLE: $.44 \times 100 = 44 \%RH$

RH Measured Vs Output Reading

% Relative Humidity	Output	
	Current(mA)	Voltage(Vdc)
5	4.8	.05
10	5.6	.10
15	6.4	.15
20	7.2	.20
25	8	.25
30	8.8	.30
35	9.6	.35
40	10.4	.40
45	11.2	.45
50	12	.50
55	12.8	.55
60	13.6	.60
65	14.4	.65
70	15.2	.70
75	16	.75
80	16.8	.80
85	17.6	.85
90	18.4	.90
95	19.2	.95



Calibration

Your transmitter has been factory calibrated to meet or exceed the specifications outlined in this manual. To maintain original specifications it is generally recommended that your transmitter be recalibrated on an annual basis depending on operating conditions.

Calibration Procedure for HX92AC

Recommended equipment:

Humidity Calibration Kit, OMEGA Model No.: HX92-CAL

Handheld Digital Multimeter, OMEGA Model No.: HHM29

DC Power Supply, OMEGA Model No.: PSU-93

1. Remove enclosure cover.
2. Connect transmitter as shown in Figure 8.
3. Apply power to transmitter and allow to warm up for 15 min.
4. Place sensor head in a "Low" 11.3% RH environment (eg. Lithium Chloride solution) and allow to stabilize for 10 min.
5. Adjust potentiometer "P3" so that the output decreases to a minimum value and further adjustment produces no change. Output should be about 4.0mA. If output is not at 4.0mA adjust potentiometer "P1" until you have an output reading of 4.0mA.
6. Adjust potentiometer "P3" to the point, but not pass, where the output just starts to increase.
7. Remove the sensor head from the "LOW" RH environment.
8. Place the sensor head in a "HIGH" 73.3% RH environment (eg. Sodium Chloride solution) and allow to stabilize for 10 min.
9. Adjust potentiometer "P2" so that the output reading is measuring 14.24mA, this is equivalent to the difference between the "LOW" and "HIGH" RH environment which is 64% RH.
10. Adjust potentiometer "P3" so that the output reading increases to 16.05mA. This is the proper output equivalent to the "HIGH" RH environment.
11. Remove the sensor head from the "HIGH" RH environment.
12. Calibration complete.




Figure 8: HX92AC Typical Calibration Setup

Calibration procedure for HX92AV

Recommended equipment:

Humidity Calibration Kit, OMEGA Model No.: HX92-CAL
 Handheld Digital Multimeter, OMEGA Model No.: HHM29
 Dc Power Supply, OMEGA Model No.: PSU-93

1. Remove enclosure cover.
2. Connect transmitter as shown in Figure 9.
3. Apply power to transmitter and allow to warm up for 15 min.
4. Place sensor head in a "Low" 11.3% RH environment (eg. Lithium Chloride solution) and allow to stabilize for 10 min.
5. Adjust potentiometer "P3" so that the output decreases to a minimum value and further adjustment produces no change. Output should be about 0.000 volts.
6. Adjust potentiometer "P3" to the point, but not pass, where the output just starts to increase.
7. Remove the sensor head from the "LOW" RH environment.



8. Place the sensor head in a "HIGH" 73.3% RH environment (eg. Sodium Chloride solution) and allow to stabilize for 10 min.
9. Adjust potentiometer "P2" so that the output reading is measuring 0.640 volts, this is equivalent to the difference between the "LOW" and "HIGH" RH environment which is 64% RH.
10. Adjust potentiometer "P3" so that the output reading increases to 0.753 volts. This is the proper output equivalent to the "HIGH" RH environment.
11. Remove the sensor head from the "HIGH" RH environment.
12. Calibration complete.




Figure 9: HX92AV Typical Calibration Setup



Maintenance

If your Humidity transmitter will be used in a dusty environment, the protective sensor filter, if clogged, may be removed for cleaning. Unscrew the protective cover and gently blow compressed air through the filter screen. A soft brush may also be used to remove dirt particles from the screen.

If the sensor is subjected to 100% condensation, it must be dried to obtain correct readings. There will be no permanent damage or calibration shift to the unit.

Units should not be exposed to high concentrations of ammonia or alcohol vapors.

Specifications

Measuring Range:	3 – 95% (non-condensing)
Accuracy:	±2.5% @ 22°C (72°F) with an added temperature coefficient error of -.06 % RH/°F (both increasing and decreasing in temperature from ambient).
Repeatability:	± 1 % RH
Operating Temperature Range:	-20 to 75 °C (-4 to 167°F)
Output:	
Model: HX92AC	4 to 20 mA (Scaled for 0 to 100% RH)
Model : HX92AV	0 to 1 Vdc (Scaled for 0 to 100% RH)
Power:	6 –30 Vdc @ 20mA
Max Loop Resistance:	Ohms = (V supply – 6 V)/.02 A
RH Time Constant (90% response at 25°C, in moving air at 1m/s):	>10 seconds, 10 to 90% RH >15 seconds, 90 to 10% RH
Sensor Type:	Thin Film Polymer Capacitor
Enclosure Housing:	Gray Polycarbonate, (IP 65, DIN 40050) NEMA rated up to 13, UL Listed.
Connections:	
Cable Strain Relief:	Nylon, Liquid-tight with neoprene gland for .09 to .265" diameter cable.
Wire Connections:	Internal 3-Position Terminal Strip. Accepts from 14 to 22 gage wire.
Dimensions:	See "Mounting" Section
Weight:	
Wall Mount Model:	82 g. (3 oz)
Duct Mount Model:	100 g. (3.5 oz)

Where Do I Find Everything I Need for Process Measurement and Control? **OMEGA...Of Course!**

Shop online at www.omega.com

TEMPERATURE

- ☑ Thermocouple, RTD & Thermistor Probes, Connectors, Panels & Assemblies
- ☑ Wire: Thermocouple, RTD & Thermistor
- ☑ Calibrators & Ice Point References
- ☑ Recorders, Controllers & Process Monitors
- ☑ Infrared Pyrometers

PRESSURE, STRAIN AND FORCE

- ☑ Transducers & Strain Gages
- ☑ Load Cells & Pressure Gages
- ☑ Displacement Transducers
- ☑ Instrumentation & Accessories

FLOW/LEVEL

- ☑ Rotameters, Gas Mass Flowmeters & Flow Computers
- ☑ Air Velocity Indicators
- ☑ Turbine/Paddlewheel Systems
- ☑ Totalizers & Batch Controllers

pH/CONDUCTIVITY

- ☑ pH Electrodes, Testers & Accessories
- ☑ Benchtop/Laboratory Meters
- ☑ Controllers, Calibrators, Simulators & Pumps
- ☑ Industrial pH & Conductivity Equipment

DATA ACQUISITION

- ☑ Data Acquisition & Engineering Software
- ☑ Communications-Based Acquisition Systems
- ☑ Plug-in Cards for Apple, IBM & Compatibles
- ☑ Datalogging Systems
- ☑ Recorders, Printers & Plotters

HEATERS

- ☑ Heating Cable
- ☑ Cartridge & Strip Heaters
- ☑ Immersion & Band Heaters
- ☑ Flexible Heaters
- ☑ Laboratory Heaters

ENVIRONMENTAL MONITORING AND CONTROL

- ☑ Metering & Control Instrumentation
- ☑ Refractometers
- ☑ Pumps & Tubing
- ☑ Air, Soil & Water Monitors
- ☑ Industrial Water & Wastewater Treatment
- ☑ pH, Conductivity & Dissolved Oxygen Instruments

M1019A/1100